



Seat must be fixed  
with self-cutting screws

\* - supporting beam  
must be fixed with  
self-cutting screws

therefore use machine  
bolt M10 x 30 mm with nut