



Seat must be fixed
with self-cutting screws

* - supporting beam
must be fixed with
self-cutting screws

therefore use machine
bolt M10 x 30 mm with nut